STATEMENT OF SIGNIFICANCE

1738 Trussler Road



1738 Trussler Road, GCT Pt Lt 149 RP 58R8498 Part 1

Huron Road, Plan 585 Lots 18, 19, and 20 Part Lots 5, 6, 7, 8, 15, 16, and 21 SS Huron Road German Company Tract Part Lot 149

Summary of Significance

⊠Social Value **☑**Design/Physical Value **⊠**Historical Value **□**Economic Value **⊠Contextual Value** □Environmental Value

Municipal Address:1738 Trussler Road (Red)

Legal Description: GCT Pt Lt 149 RP 58R8498 Part 1

Year Built: 1879

Architectural Style: Ontario Gothic Revival

Original Owner: John Chapman Jr.

Original Use: Farm Condition: Good

Description of Cultural Heritage Resource

The property municipally addressed as 1738 Trussler Road is a one-and-one-half storey late 19th century brick farmhouse built in the Ontario Gothic Revival architectural style. The property on Huron Road is a late 19th century farm with outbuildings. The farmhouse is situated on a 0.92 acre parcel of land located on the east side of Trussler Road between Huron Road and Plains Road while the outbuildings are situated on a 62.39 acre parcel of land located at the south east corner of Trussler Road and Huron Road in the South Plains Planning Community of the City of Kitchener within the Region of Waterloo. The principal resource that contributes to the heritage value is the farmhouse, and adjacent outbuildings, specifically the barn, located on Huron Road, and legally described as LT 17 S/S HURON RD, 18 S/S HURON RD, 19 S/S HURON RD, 20 S/S HURON RD PL 585 TWP OF WATERLOO; PT LT 3 S/S HURON RD, 4 S/S HURON RD, 5 S/S HURON RD, 6 S/S HURON RD, 7 S/S HURON RD, 8 S/S HURON RD, 15 S/S HURON RD, 16 S/S HURON RD, 21 S/S HURON RD PL 585 TWP OF WATERLOO; PT LT 149 GERMAN COMPANY TRACT KITCHENER AS IN 1200696 & 1200697, SAVE & EXCEPT PT 12 ON 58R-16920; KITCHENER.

Heritage Value

1738 Trussler Road is recognized for its design/physical, historical/associative, and contextual values.

Design/Physical Value

The property municipally addressed as 1738 Trussler Road demonstrates design/physical value as a representative example of a late-19th century brick farmhouse built in the Ontario Gothic Revival architectural style. The 1851 Manuscript Census suggests that a one-storey log structure was covered or replaced by the existing building. The building has many intact heritage attributes in good condition.

Front (West) Façade

The front façade faces Trussler Road and contains three bays. The building features: side-gable roof with a central Gothic dormer; buff (yellow) brick laid in the stretcher bond style; second floor pointed arch (lancet) door and door opening with brick hoodmould with corbel stops; central verandah on the first and second floor; second floor verandah features square newel posts with ball caps, and simple top and bottom rails with square balusters; first floor verandah features highly decorative posts and pilasters with scroll brackets and moulded frieze; front door with segmentally arched transom; two segmentally arched windows, window openings and storm windows with brick voussoirs and wood sills; and, fieldstone foundation.

Side (South) Façade

The side façade faces south and contains two bays plus a kitchen annex, which may have been original to the house. The first two bays feature: side-gable roof divided by a concrete block chimney; buff (yellow) brick construction; two 1/1 double hung flat head windows with segmentally arched window openings with brick voussoirs and wood sills on the second storey; two 2/2 double hung segmentally arched windows, window openings and storm windows with brick voussoirs and wood sills; and, a stone foundation. The kitchen annex features: cross-gable roof with a central Gothic dormer; buff (yellow) brick laid in the stretcher bond style; second floor pointed arch (lancet) window and window opening; first storey verandah with a hip roof and highly decorative posts pilasters with scroll brackets and moulded frieze; segmentally arched door and door opening with brick voussoirs; one 2/2 double hung segmentally arched window, window opening and storm window with brick voussoirs and wood sills; and, stone foundation. Another addition is in the rear but has limited visibility from the public realm.

Side (North) Façade

The side façade faces north and features: side-gable roof; two 1/1 double hung flat head windows with segmentally arched window openings with brick voussoirs and wood sills on the second storey; two 2/2 double hung segmentally arched windows, window openings and storm windows with brick voussoirs and wood sills; and, a stone foundation. The kitchen annex to the rear has limited visibility from the public realm.

Interior Value

The interior design/physical values were originally described in a document entitled "Architectural Analysis – 1738 Trussler Road" written by Don Ryan on June 7, 1991, and based on this research are further described below.

An unusual total of seven doors and one dog leg staircase in the kitchen may indicate that this section was an original dwelling. There is original wainscotting and panelled doors with original knobs and latches inside. The rooms remain divided as originally laid out. There is an enclosed, plain staircase directly before the front entrance. Original plaster clads the walls, and the door and baseboards mouldings remain intact. There is an interesting original moulded arch between the kitchen and the main house.

Other Buildings

The original barn with gable roof, vertical board siding, original hardware and stone foundation is located south of the house on a separate parcel of land. A new garage was constructed in 1999 that does not detract from the character of the farmhouse, barn or immediate surroundings.

Historical/Associative Value

The property municipally addressed as 1738 Trussler Road has historical/associative value due to its history and association with early settlement, Daniel and Jacob Erb, Joseph Bamburger, John Chapman, Reuben Eby, Simon Hallman, Ida Hallman, and the Trussler family.

Daniel and Jacob Erb sold the land to Joseph Bamburger in 1805 who then sold to John Chapman in 1848. John Chapman Sr., born in 1811, came to Canada from England in the mid-1840's with his wife Lydia and his two children. A third child, John Jr., was born in Upper Canada in 1846. The 1851 manuscript census indicates that the Chapman family resided in a one-storey log structure. It is assumed that the brick structure either replaced or covered the log structure. John Chapman sold the land to Reuben Eby in 1907 who then sold the land to Simon Hallman (b. August 28, 1886, d. May 21, 1976) in 1930. Simon married his wife, Ida Hallman (b. October 24, 1902, d. May 25, 1991), on December 18, 1923. The lands passed to Ida in 1955 and were sold to Trussler Farms in 1977.

Contextual Value

The contextual values relate to how the property helps to maintain and support the rural character of the area. The farmhouse remains on its original location. A board and batten front gable garage contributes to the character of the property along with the cedar hedges delineating three sides of the property. The farmhouse is visually and historically linked to its surroundings, especially the rural farm property on the corner of Huron Road and Trussler Road where the original barn and driveshed still stand. This property is addressed off Huron Road (outlined in green on page 1) and legally described as Plan 585 Lots 18, 19, and 20 Part Lots 5, 6, 7, 8, 15, 16, and 21 SS Huron Road German Company Tract Part Lot 149.

Heritage Attributes

The heritage value of 1738 Trussler Road resides in the following heritage attributes:

- All elements related to the design/physical value of the brick house built in the Ontario Gothic Revival architectural style, including:
 - o one-and-one-half storey height;
 - o rectangular plan with rear kitchen annex;
 - front façade with three bays;
 - o side façade with two bays and rear kitchen annex;
 - o side-gable roof and kitchen annex both with a central Gothic dormer;
 - buff (yellow) brick laid in the stretcher bond style;
 - half storey pointed arch (lancet) door and door opening with brick hoodmould with corbel stops;
 - half story pointed arch (lancet) window and window opening with hoodmould with corbel stops;
 - o central verandah on the first and half storey;
 - half storey verandah features square newel posts with ball caps, and simple top and bottom rails with square balusters;
 - o first storey verandah features highly decorative posts and pilasters with scroll brackets and moulded frieze;
 - o first storey verandah on the kitchen annex with a hip roof and highly decorative posts pilasters with scroll brackets and moulded frieze;
 - o front door with segmentally arched transom;
 - 2/2 double hung segmentally arched windows, window openings and storm windows with brick voussoirs and wood sills;
 - 1/1 double hung flat head windows, window openings and storm windows with brick voussoirs and wood sills; and,
 - fieldstone foundation.
- All elements related to the design/physical value of interior of the farmhouse, including:
 - dog leg staircase;
 - original wainscotting;
 - o original panelled doors with original knobs and latches
 - original layout of rooms;
 - o enclosed, plain staircase directly before the front entrance;
 - original plaster;
 - o door and baseboards mouldings; and,
 - o an interesting original moulded arch between the kitchen annex and the main farmhouse.

References

Burmaster, G. (2008). *Municipal Heritage Register – Written Response Form*. City of Kitchener: Kitchener, ON.

86.22925247h,52.68870417t,360r/data=CowBGmISXAolMHg4ODJjMGE0MjRjMmUzYWM5OjB4ZmMwMzQ5ZWZmMGI0MjU2YxnpMYCmFLBFQCFfoFoz6CBUwCohMTczOCBUcnVzc2xlciBSb2FkLC

<u>BLaXRjaGVuZXIsIE9OGAIgASImCiQJzSfvEzqxRUAR1ArBVcuwRUAZxz6yPdEgVMAh4T0Pa3AhVMA</u> [Accessed 2024, April 5).

Hallman, J. (1991). Hallman Family History in Canada. Mrs. Joan Hallman: Kitchener, ON.

Shantz, C. (1980). 1738 Trussler Road. City of Kitchener: Kitchener, ON.

Simpson, S. (1981). 1738 Trussler Road. City of Kitchener: Kitchener, ON.

Photographs



Front Elevation (West Facade) - 1738 Trussler Road



Front and Side Elevation (West and North Façade) - 1738 Trussler Road



Front and Side Elevation (West and South Façade) – 1738 Trussler Road



Front Elevation (West Façade) of New Board and Batten Garage – 1738 Trussler Road



Wide Angle View of the Frontage of the Property, including the Front Elevation (West Façade) of the Farmhouse – 1738 Trussler Road



View of Farmhouse (1738 Trussler Road) & Barn and Driveshed (Huron Road)



Jean Haalboom

CULTURAL HERITAGE EVALUATION FORM

1478 Trussler Road

Address:		Recorder:
Description: (date of construction, architectural Photographs Attached:	rural small house style, etc) içade □ Right Façade □ Rear Facade	March 21, 2023 Date: Partial Setting
Designation Criteria	Recorder – Heritage Kitchener Committee	Heritage Planning Staff
1. This property has design value or physical value because it is a rare, unique, representative or early example of a style, type, expression, material or construction method.	N/A □ Unknown □ No □ Yes ⊠	N/A □ Unknown □ No □ Yes ⊠
2. The property has design value or physical value because it displays a high degree of craftsmanship or artistic merit.	N/A □ Unknown □ No ⊠ Yes □	N/A □ Unknown □ No ⊠ Yes □
3. The property has design value or physical value because it demonstrates a high degree of technical or	N/A □ Unknown □ No ⊠ Yes □	N/A □ Unknown ⊠ No □ Yes □



	scientific achievement. * E.g constructed with a unique material combination or use, incorporates challenging geometric designs etc.				
4.	The property has historical value or associative value because it has direct associations with a theme, event, belief, person, activity, organization or institution that is significant to a community. * Additional archival work	N/A □ Yes ⊠	Unknown □ No □	N/A □ Yes ⊠	Unknown □ No □
	may be required.				
5.	The property has historical or associative value because it yields, or has the potential to yield, information that contributes to an understanding of a community or culture. * E.g - A commercial building may provide an understanding of how the economic development of the City occured. Additional archival work may be required.	N/A □ Yes ⊠	Unknown No	N/A □ Yes ⊠	Unknown □ No □
6.	The property has historical value or associative value because it demonstrates or	N/A □ Yes □	Unknown □ No ⊠	N/A □ Yes □	Unknown □ No ⊠



reflects the work or ideas of an architect artist, builder, designer or theorist who is significant to community. * Additional archival wormay be required.		
7. The property has contextual value because it is important in definin maintaining or supporting the character of an area * E.g It helps to define an entrance point to a neighbourhood or helps establish the (historic) rural character of an area		N/A □ Unknown □ No □ Yes ⊠
8. The property has contextual value because it is physically, functionally, visually or historically linked to its surroundings. * Additional archival wor may be required.	N/A □ Unknown □ No □ Yes ☑	N/A □ Unknown □ No □ Yes ⊠
9. The property has contextual value because it is a landmark. *within the region, city of neighborhood.	N/A □ Unknown □ No ⊠ Yes □	N/A □ Unknown □ No ⊠ Yes □

Notes

M. Drake: see "Architectural Analysis -1478 Trussler Road" written by Don Ryan on June 5, 1991; see "Cultural Heritage Background Study: Built Heritage and Cultural Heritage Landscapes: Southwest Kitchener Urban Area Study" written by Nancy Z. Tausky in August 2010

J. Haalboom: main house, blue siding, windows modern, landscape, trees



Additional	Recorder	Heritage Kitchener Committee		
Criteria				
Interior: Is the interior arrangement, finish, craftsmanship and/or detail noteworthy?	N/A □ Unknown ⊠ No □ Yes □	N/A □ Unknown □ No □ Yes ⊠		
Completeness: Does this structure have other original outbuildings, notable landscaping or external features that complete the site?	N/A □ Unknown ⊠ No □ Yes □	N/A □ Unknown □ No □ Yes ⊠		
Site Integrity: Does the structure occupy its original site? * If relocated, is it relocated on its original site, moved from another site, etc.	N/A □ Unknown □ No □ Yes ⊠	N/A □ Unknown □ No □ Yes ⊠		
Alterations: Does this building retain most of its original materials and design features? Please refer to the list of heritage attributes within the	N/A □ Unknown □ No □ Yes ⊠	N/A □ Unknown □ No □ Yes ⊠		



Statement of Significance and indicate which elements are still existing and which ones have been removed.		
Alterations: Are there additional elements or features that should be added to the heritage attribute list?	N/A □ Unknown □ No ⊠ Yes □	N/A □ Unknown ⊠ No □ Yes □
Condition: Is the building in good condition? *E.g Could be a good candidate for adaptive reuse if possible and contribute towards equitybuilding and climate change action.	N/A □ Unknown □ No □ Yes ⊠	N/A □ Unknown □ No □ Yes ⊠
Indigenous History: Could this site be of importance to Indigenous heritage and history? *E.g Site within	N/A □ Unknown ☒ No □ Yes □ □ Additional Research Required	N/A □ Unknown ⊠ No □ Yes □ □ Additional Research Required
300m of water sources, near distinct	N/A □ Unknown ⊠ No □ Yes □	N/A □ Unknown □ No ⊠ Yes □



topographical land, or near cemeteries might have archaeological potential and indigenous heritage potential.	☐ Additional Research Required	☐ Additional Research Required
Could there be any urban Indigenous history associated with the property?		
* Additional archival work may be required.		
Function: What is the present function of the subject property?	Unknown □ Residential ⊠ Commercial □ Office □ Other □ -	Unknown □ Residential ⊠ Commercial ⊠ Office □ Other ⊠ Farm
* Other may include vacant, social, institutional, etc. and important for the community from an equity building perspective.		
Diversity and Inclusion: Does the subject property	N/A □ Unknown ☒ No ☒ Yes □ □ Additional Research Required	N/A □ Unknown □ No ☒ Yes □ □ Additional Research Required
contribute to the cultural heritage of a community of people?	N/A □ Unknown ⊠ No □ Yes □ □ Additional Research Required	N/A □ Unknown □ No ☒ Yes □ □ Additional Research Required



Does the subject property have intangible value to a specific community of people? * E.g Waterloo Masjid (Muslim Society of Waterloo & Wellington Counties) was the first established Islamic Center and Masjid in the Region and contributes to the history of the Muslim community in the	
1	
area.	
	o far off road to assess, can't see smoke house, in good condition based on what can be
M. Drake: see "A" "Cultural Heritag	Architectural Analysis -1478 Trussler Road" written by Don Ryan on June 5, 1991; see ge Background Study: Built Heritage and Cultural Heritage Landscapes: Southwest Area Study" written by Nancy Z. Tausky in August 2010, log house is covered by sidding
<u>Recommen</u>	<u>dation</u>
	ty meet the definition of a significant built heritage resource, and should it nder Part IV of the Ontario Heritage Act? (Does it meet two or more of the ria?)
N/A □ Unknow	vn □ No □ Yes ⊠
If not, please sele	ect the appropriate action for follow-up
·	Municipal Heritage Register
•	



☐ Additional Research Required	
Other:	
General / Additional Notes	
J. Haalboom: age and material and family (Trussler) should qualify for designation, re arrange with owner/resident for the visit	quires reassessment -
M. Drake: assessments provided in 1991 and 2010, see "Architectural Analysis -1478 by Don Ryan on June 5, 1991; see "Cultural Heritage Background Study: Built Heritage Heritage Landscapes: Southwest Kitchener Urban Area Study" written by Nancy Z. Tal	e and Cultural
TO BE FILLED BY HERITAGE PLANNING STAFF:	
Date of Property Owner Notification:	