

PHOTOGRAPHS



Photo 1. Front (North) Elevation in 2020



Photo 2. Front (North) Elevation in 2020



Figure 3. North-West Corner in 2020



Figure 4. Side (West) Elevation in 2020



Figure 5. Side (East) Elevation in 2020



Figure 6. North-West Corner in 2023



Figure 7. Side (West) Elevation in 2023



Figure 8. Side (West) Elevation in 2023



Figure 9. Side (East) Elevation in 2023



Figure 10. Side (East) Elevation in 2023




Figure 11. Interior – Buckled Wood Floor in 2023



Figure 12. Interior – Water Damaged Wood Floor in 2023



Figure 13. Interior – Example of Peeling Paint in 2023



Figure 14. Interior – Bathroom Floor in 2023



Figure 15. Interior – Floor in 2023



Figure 16. Interior – Water Damaged Ceiling in 2023



Figure 17. Interior – Water Damaged Ceiling in 2023



Figure 18. Interior – Stairs to Basement in 2023



Figure 19. Front (North) Elevation in 2024



Figure 20. Front (North) Elevation in 2024



Figure 21. Front (North) Elevation in 2024



Figure 22. Porch Roof and Columns in 2024



Figure 23. North-West Corner in 2024



Figure 24. Side (East) Elevation in 2024



Figure 25. Side (East) Elevation in 2024



Figure 26. Hole in Clapboard on Side (East) Elevation in 2024



Figure 27. Side (East) Elevation in 2024



Figure 28. Missing Fascia from Chimney Removal on Side (East) Elevation in 2024



Figure 29. Example Leaded Glass Diamond Shaped Windows in 2024